



(AHU1B Control Center Penthouse)

Bottom right overload heater connection extremely overheating.

Sp1 224.4 F

Sp2 136.4 F